



Forest Service
U.S. DEPARTMENT OF AGRICULTURE

Forest Products Laboratory | Research Note FPL–RN–0425 | February 2024

Condition Assessment of Wood Members in a Historic Building at the Veterans Affairs Medical Center in Tomah, Wisconsin

Robert J. Ross
Laurice M. Spinelli Correa



Abstract

The USDA Forest Service, Forest Products Laboratory, was asked to inspect the main support timbers of a historic building at the Veterans Affairs (VA) Medical Center in Tomah, Wisconsin. This report summarizes the results obtained from the inspection and assessment. It includes a summary of observations, wood species identification, and recommendations.

Keywords: Condition assessment, visual inspection, decay, moisture, timbers

Contents

Introduction 1

History of Tomah VA Building 23..... 1

Inspection of Tomah VA Building 23..... 1

Wood Species Identification and Properties..... 2

Significance of Effect of Decay on Mechanical Properties of Wood 2

Results..... 2

Conclusions 6

Literature Cited 6

Additional References..... 7

February 2024

Ross, Robert J.; Spinelli Correa, Laurice M. 2024. Condition assessment of wood members in a historic building at the Veterans Affairs Medical Center in Tomah, Wisconsin. Research Note FPL-RN-0425. Madison, WI: U.S. Department of Agriculture, Forest Service, Forest Products Laboratory. 7 p. <https://doi.org/10.2737/FPL-RN-425>

This and many other Forest Service research publications are available for download through TreeSearch at <https://www.fs.usda.gov/treesearch/>.

The Forest Products Laboratory is maintained in cooperation with the University of Wisconsin.

The use of trade or firm names in this publication is for reader information and does not imply endorsement by the United States Department of Agriculture (USDA) of any product or service.

In accordance with Federal civil rights law and U.S. Department of Agriculture (USDA) civil rights regulations and policies, the USDA, its Agencies, offices, and employees, and institutions participating in or administering USDA programs are prohibited from discriminating based on race, color, national origin, religion, sex, gender identity (including gender expression), sexual orientation, disability, age, marital status, family/parental status, income derived from a public assistance program, political beliefs, or reprisal or retaliation for prior civil rights activity, in any program or activity conducted or funded by USDA (not all bases apply to all programs). Remedies and complaint filing deadlines vary by program or incident.

Persons with disabilities who require alternative means of communication for program information (e.g., Braille, large print, audiotope, American Sign Language, etc.) should contact the responsible Agency or USDA's TARGET Center at (202) 720-2600 (voice and TTY) or contact USDA through the Federal Relay Service at (800) 877-8339. Additionally, program information may be made available in languages other than English.

To file a program discrimination complaint, complete the USDA Program Discrimination Complaint Form, AD-3027, found online at http://www.ascr.usda.gov/complaint_filing_cust.html and at any USDA office or write a letter addressed to USDA and provide in the letter all of the information requested in the form. To request a copy of the complaint form, call (866) 632-9992. Submit your completed form or letter to USDA by: (1) mail: U.S. Department of Agriculture, Office of the Assistant Secretary for Civil Rights, 1400 Independence Avenue, SW, Washington, D.C. 20250-9410; (2) fax: (202) 690-7442; or (3) email: program.intake@usda.gov.

USDA is an equal opportunity provider, employer, and lender.

Condition Assessment of Wood Members in a Historic Building at the Veterans Affairs Medical Center in Tomah, Wisconsin

Robert J. Ross, Supervisory Research General Engineer (retired)
USDA Forest Service, Forest Products Laboratory, Madison, Wisconsin, USA

Laurice M. Spinelli Correa, Assistant Research Professor
Mississippi State University, Starkville, Mississippi, USA

Introduction

The USDA Forest Service, Forest Products Laboratory (FPL), was contacted in 2022 by Stone Group Architects, Inc. (Sioux Falls, SD), to assist in assessing the condition of timbers in a historic building (Building 23, Fig. 1) at the Veterans Affairs (VA) Medical Center in Tomah, Monroe County, Wisconsin. The objective of the work summarized in this report was to assess the condition of the structural timbers that support the building. A visual inspection of the timbers and other wood structural elements was conducted on October 25–26, 2022.

History of Tomah VA Building 23

Tomah Indian Industrial School

Building 23 was originally the boy's dormitory for the Tomah Indian Industrial School in Wisconsin. It is a wood-framed structure, constructed in the 1890s using lumber and timbers from local forests. The school was established in 1891 and opened in 1893. This boarding school was relatively small (150 students and 5 staff in 1899). The school closed in 1941. More than 2,000 students were admitted during the existence of the school.

Army Air Force Radio Technical School

The Army Air Force Radio Technical School was activated on November 30, 1942, to conduct technical training for U.S. Army Air Forces. The 1000 Technical School Squadron (Special) provided technical training to personnel, including radio interception techniques and radio maintenance and operations. Housed in Building 23, it functioned as a sub-base of the radio school at Truax Army Airfield in Madison, Wisconsin, which itself was part of Central (later Eastern) Technical Training Command. The radio school at Tomah was inactivated on April 1, 1944. The facility was transferred to Air Technical Service Command on April 30, 1944. It was then transferred as inactive to the U.S. Army Corps of Engineers on April 1, 1946, for disposition. The airfield associated with the school was turned over to civil control through War Assets Administration (WAA).

Inspection of Tomah VA Building 23

An in-depth, nondestructive inspection of Building 23 was conducted on October 25–26, 2022. Accepted inspection techniques commonly used for wood structures are



Figure 1—Building 23, Tomah VA Medical Center.

Table 1—Species of the samples collected on-site

Sample no.	Common name	Species
1	Douglas-fir	<i>Pseudotsuga menziesii</i>
2	Red pine	<i>Pinus resinosa</i>
3	White pine	<i>Pinus strobus</i>
4	Red pine	<i>Pinus resinosa</i>
5	Douglas-fir	<i>Pseudotsuga menziesii</i>
6	Douglas-fir	<i>Pseudotsuga menziesii</i>
7	Red pine	<i>Pinus resinosa</i>
8	Red pine	<i>Pinus resinosa</i>

discussed in detail by White and Ross (2014). The simplest method for locating deterioration in wood members is visual inspection. An inspector observes the structure for signs of actual or potential deterioration, noting areas that require further investigation. Visual inspection is useful for detecting intermediate or advanced surface decay, water damage, mechanical damage, or failed members. Visual inspection cannot detect early-stage decay or deterioration.

During visual inspection, the inspector looks for several key indicators: fruiting bodies (evidence of advanced decay), staining or discoloration of members (indicators of water damage), evidence of insect activity (holes, frass, and powder posting), plant or moss growth in a member, deep checks or splits, and failed or missing members.

In our visual inspection of the wood members of Building 23, we specifically looked for

1. evidence of water intrusion and subsequent damage, especially where the timbers were in contact with the foundation and other areas where the wood members were compromised, and
2. evidence of structural failure of the timbers.

Wood Species Identification and Properties

Building 23 is a wood-framed structure. Based on its age, we believe it was constructed mainly from lumber and timbers from local and regional tree species. Samples from timbers and lumber in the structure were collected and sent to FPL for species identification. Specimens were either eastern white pine, red pine, or Douglas-fir (*Pinus strobus*, *Pinus resinosa*, or *Pseudotsuga menziesii*, respectively). Eastern white and red pine are species that grow in the surrounding area. Douglas-fir grows in the western United States and is commonly used in structural applications. We believe that this species was not part of the original structure but was used in later repairs or building modifications. Table 1 lists samples collected on-site, and Table 2 summarizes some important physical and mechanical properties of these three species. Markwardt and Wilson (1935) summarized one of the first studies at FPL (dating to

1910). The study was designed to establish the properties of 164 species of wood grown in the United States. The test methodologies developed at FPL as part of this fundamental study serve as the basis for the current standardized methods for establishing baseline properties.

Significance of Effect of Decay on Mechanical Properties of Wood

The presence of deterioration caused by decay has significant effects on various properties of structural timbers. The following sections summarize the effects of decay on various strength properties of wood, and Table 3 references the early scientific literature on these effects.

Toughness (Impact Bending)

Toughness, the ability of a wood member to withstand shock loading, is generally considered to be the strength property most affected in early stages of decay. Research dating to 1954 indicates that a loss of only 1% in weight corresponds to a toughness loss of up to 50%.

Static Bending

Research dating to the 1930s has been conducted on modulus of elasticity, modulus of rupture, and work-to-maximum-load in bending mode. Reported results indicated a significant loss in modulus of rupture (strength) after wood had decayed.

Other Strength Properties

Research has shown that compression perpendicular to the grain, compression parallel to the grain, tension parallel to the grain, shear parallel to the grain, and tangential hardness are also impacted by deterioration caused by decay.

Results

Based on our visual inspection, we found the building's condition to be cause for immediate concern. The basement of the building has considerable water damage. The water damage can be seen throughout outside walls, basement internal walls, timber beams, wood framing members, and wooden floors. Figure 2 shows one of the outside walls where a crack extends from the foundation to the roof. Figure 3 shows an exterior view of the building's foundation. Note that the foundation wall is bowing outward.

Water damage was observed in most rooms. Room 02333 presented the worst damage in the building, with severe wood decay and wood and paint discoloration, both caused by high moisture and humidity levels. Figures 4 and 5 show two of the damaged timber beams, and Figure 6 shows water infiltration on the floor system above the basement. Room 02336 was also severely affected by water damage, with evident mold, discoloration, and deteriorated members (Figs. 7 and 8). In addition to the water damage, mechanical failures can also be observed in the basement of the

Table 2—Some physical and mechanical properties of clear wood (no decay) from eastern white pine, red pine, and Douglas-fir species.^a

Common name	Scientific name	Specific gravity		Modulus of elasticity ($\times 10^6$ lb/in ²)		Bending strength (lb/in ²)		Compression strength, perpendicular to grain (lb/in ²)	
		Green	12% MC	Green	12% MC	Green	12% MC	Green	12% MC
Eastern white pine	<i>Pinus strobus</i>	0.34	0.35	0.99	1.24	4,900	8,600	220	440
Red pine	<i>Pinus resinosa</i>	0.41	0.46	1.28	1.63	5,800	11,000	260	600
Douglas-fir	<i>Pseudotsuga menziesii</i>	0.45	0.48	1.56	1.95	7,700	12,400	380	800

Table 3—Estimated values for strength losses in softwoods and hardwoods at early stages of decay (indicated by weight loss) by brown-rot and white-rot fungi as a percentage of the value for nondecayed samples^{a,b}

Strength property loss (%)											
Approx. weight loss (%)	Tough- ness	Impact bending	General bending strength	Static bending			Com- pression perpen- dicular (radial)	Com- pression parallel	Tension parallel	Shear parallel	Hardness
				Work to max. load	MOR ^c	MOE ^c					
Brown-rot											
Softwoods											
1	57	20–38	—	—	—	—	—	—	—	2	—
2	—	20–50	5	27	13–50	4–55	18–24	10	23–40	—	—
4	75	25–55	—	—	—	—	25–35	—	—	6	7
6	—	62–72	16	—	61	6	48	25	60	—	—
8	—	78	—	—	—	—	48–60	—	50	15	21
10	—	85	36	—	70	—	66	45	—	20	—
Hardwoods											
1	—	6–27	—	—	—	—	—	—	—	—	—
2	36	31–50	—	54	32	—	6–10	—	56	—	—
4	—	60–70	—	69	49	—	—	—	—	—	—
6	—	80	—	75	61	—	16–25	—	—	—	—
8	—	9–89	13–34	—	—	—	19	—	82	—	—
10	60	70–92	—	—	—	—	—	—	—	—	—
White-rot											
Softwoods											
1	55	—	—	—	—	—	—	—	—	—	—
2	—	—	—	—	—	—	10–20	—	4–38	—	—
4	—	—	—	—	—	—	—	—	8–43	—	—
6	75	—	—	—	—	—	32–61	—	10–49	—	—
8	—	—	—	—	—	—	—	—	14–58	—	—
10	85	—	—	—	—	—	—	—	20–63	—	—
Hardwoods											
1	—	21	—	—	—	—	4	—	—	—	—
2	—	26	—	28–35	13–14	4	5	—	22–42	—	—
4	70	44	—	38	20	—	—	—	17–44	—	—
6	75	50	—	45–53	20–27	10	12–27	14	12–58	—	18
8	—	—	—	—	—	—	—	—	14–49	—	—
10	85	60	—	58	24	14	35	20	20–50	—	25

^aFrom Wilcox (1978). Values obtained from published experimental results and adjusted to equivalent weight loss levels.^bSources: Brown (1963), Cartwright and others (1931), Gillwald and Michalak (1963), Hartley (1958), Henningsson (1967), Kennedy (1958), Kennedy and Ifju (1962), Kubiak and Kerner (1963), Mizumoto (1966), Mulholland (1954), Pechmann and Schaile (1950), Richards (1954), Scheffer (1936), Toole (1971), and Wilcox (1968).^cMOR, modulus of rupture; MOE, modulus of elasticity.



Figure 2—Outside wall. Note crack that extends from the foundation to the roof.



Figure 3—Outside wall. Note outward bowing of the foundation.



Figure 4—Room 02333, decayed timber beam and water-damaged floor system.



Figure 5—Room 02333, decayed timber beam.



Figure 6—Room 02333, water-damaged floor system.



Figure 7—Room 02336, water damage.



Figure 8—Room 02336, wall damage.



Figure 12—Room 02305. Member shifting off-center.



Figure 9—Room 02305. Note horizontal split in timber beam.



Figure 10—Room 02305. Note horizontal split in timber beam (upper right of photo).



Figure 13—Room 02305. Note horizontal splits surrounding bolt.



Figure 11—Room 02305. Note that bolt is not in contact with the timber member.

building. Figures 9 and 10 show two wood beams in room 02305 with splitting in the neutral axis going all the way along the longitudinal direction of the beam. Although surface checking is common in wood members, the magnitude of splitting we observed indicates a horizontal shear failure. The horizontal shear capacity of this timber is severely compromised.

Examination of timbers in room 02305 revealed that several bolts and washers were no longer in contact with the timber (Fig. 11), which may indicate internal deterioration of the timber. We also observed some shifting of members and gap openings (Figs. 12 and 13).

Conclusions

The following conclusions are based on our visual inspection of Building 23, Tomah VA Medical Center:

1. Many structural members in Building 23 are deteriorated.
2. Several areas of decay are evident, but with the state-of-the-art in timber inspection, an accurate in-place determine of the extent to which the decay has spread would be difficult.
3. FPL has no data or published reports that specifically relate to design values for decayed wood. The results of several publications relating to the stiffness and strength of nondecayed and decayed clear-wood specimens are summarized in this report. Based on those studies, we assume that decayed wood has zero load-carrying capacity.
4. We offer no conclusions related to the stiffness or strength of decayed timbers in Building 23.
5. We can state with certainty that the load-carrying capacity of the building has been compromised, but the residual load-carrying capacity is unknown.
6. It is difficult to estimate the quantity or quality of recoverable material from the timbers. Many of the members are deteriorated, and they should not be reused in any load-bearing application.

Recommendations

1. If Building 23 is dismantled and reuse of the materials is desired, then each member should be evaluated using nondestructive assessment procedures.
2. None of the members should be reused in any load-bearing application.

Literature Cited

- Brown, F.L. 1963. A tensile strength test for comparative evaluation of wood preservatives. *Forest Products Journal*. 13(9): 405–412.
- Cartwright, K.St G.; Findlay, C.J.; Campbell, W.G. 1931. The effect of progressive decay by *Trametes serialis* Fr. on the mechanical strength of the wood of Sitka spruce. *Forest Products Research Bulletin* No. 11. Great Britain: Department of Scientific and Industrial Research.
- FPL. 2021. Wood handbook: wood as an engineering material. General Technical Report FPL–GTR–282. Madison, WI: U.S Department of Agriculture, Forest Service, Forest Products Laboratory. 543 p.
- Gillwald, W.; Michalak, J. 1963. Vergleichende Untersuchungen über die Einwirkung von verschiedenen holzerstorenden Pilzen auf einige physikalische Eigenschaften und die Festigkeit des Pappelholzes (*Populus marilandica* Bosc.). *Wiss.Z. Humboldt-Univ. Berlin, Math. Naturwiss. Reihe*. 12(2): 265–273.
- Hartley, C. 1958. Evaluation of wood decay in experimental work. USDA Forest Products Laboratory Mimeo No. 2119.
- Henningsson, B. 1967. Changes in impact bending strength, weight, and alkali solubility following fungal attack on birch wood. *Stud. For. Suec.* (Stockholm). No. 41.
- Kennedy, R.W. 1958. Strength retention in wood decayed to small weight losses. *Forest Products Journal*. 8(10): 308–314.
- Kennedy, R.W.; Ifju, G. 1962. Applications of microtensile testing of thin wood sections. *Tappi*. 45(9): 725–733.
- Kubiak, M.; Kerner, G. 1963. Die Veränderungen einiger physikalischer Eigenschaften, der Druckfestigkeit und der chemischen Zusammensetzung des Holzes durch *Conophora cerebella* Pers. und *Steveum hirsutum* Wiid. *Drev. Vysk.* 1963(4): 181–193.
- Markwardt, L.J.; Wilson, T.R.C. 1935. Strength and related properties of woods grown in the United States. USDA Technical Bulletin No. 479. Washington, DC: United States Department of Agriculture.
- Mizumoto, S. 1966. The effect of decay caused by *Gloeophyllum trabeum* on the strength properties of Japanese red pine sapwood. *Journal of Japan Forestry Society*. 48(1): 711.
- Mulholland, J.R. 1954. Changes on weight and strength of Sitka spruce associated with decay by a brown-rot fungus, *Poria monticola*. *Journal of the Forest Products Research Society*. 4(6): 410–416.
- Pechmann, H. von; Schaile, O. 1950. Über die Andeerung der dynamischen Festigkeit und der chemischen Zusammensetzung des Holzes durch den Angriff holzerstorender Pilze. *Forstwiss Centralbl.* 69(8): 411–466. <https://doi.org/10.1007/BF01814845>
- Richards, D.B. 1954. Physical changes in decaying wood. *Journal of Forestry*. 52: 260–265.
- Scheffer, T.C. 1936. Progressive effects of *Polyporus versicular* on the physical and chemical properties of red gum sapwood. USDA Technical Bulletin No. 527. Washington, DC: U.S. Department of Agriculture.
- Toole, E.R. 1971. Reduction in crushing strength and weight associated with decay by brown rot fungi. *Wood Science*. 3(3): 172–178.
- White, R.H.; Ross, R.J. 2014. Wood and timber condition assessment manual. Second edition. General Technical Report FPL–GTR–234. Madison, WI: U.S. Department of Agriculture, Forest Service, Forest Products Laboratory. 102 p. <https://doi.org/10.2737/FPL-GTR-234>
- Wilcox, W.W. 1968. Changes in wood microstructure through progressive stages of decay. Research Paper FPL–RP–70. Madison, WI: U.S. Department of Agriculture, Forest Service, Forest Products Laboratory.

Additional References

- Allison, R.B.; Wang, X.; Ross, R.J. 2008. Visual and nondestructive evaluation of red pines supporting a ropes course in the USFS Nesbit Lake Camp, Sidnaw, MI. Proceedings, 15th Nondestructive Testing of Wood Symposium, September 10–12, 2007, Duluth, MN. Madison, WI: Forest Products Society: 43–48.
- Brashaw, B.K.; Vatalaro, R.J.; Wang, X.; Ross, R.J.; Wacker, J.P. 2005. Condition assessment of timber bridges. 2. Evaluation of several stress wave tools. General Technical Report FPL–GTR–160. Madison, WI: U.S. Department of Agriculture, Forest Service, Forest Products Laboratory. 11 p. <https://doi.org/10.2737/FPL-GTR-160>
- Clausen, C.A.; Ross, R.J.; Forsman, J.W.; Balachowski, J.D. 2001. Condition assessment of roof trusses of Quincy mine blacksmith shop in Keweenaw National Historical Park. Research Note FPL–RN–0281. Madison, WI: U.S. Department of Agriculture, Forest Service, Forest Products Laboratory. 4 p.
- Dundar, T.; Ross, R.J. 2012. Condition assessment of a 2,500-year-old mummy coffin. Research Note FPL–RN–0327. Madison, WI: U.S. Department of Agriculture, Forest Service, Forest Products Laboratory. 3 p.
- Emerson, R.; Pollock, D.; McLean, D.; Fridley, K.; Pellerin, R.; Ross, R.J. 2002. Ultrasonic inspection of large timber bridge members. *Forest Products Journal*. 52(9): 88–95.
- França, F.J.N.; Amorim França, T.S.F.; Yeary, L.A.; Hohnholt, C.; Forsman, J.W.; Ross, R.J. 2015. Condition assessment of a historic trout rearing station in upper Michigan. Research Note FPL–RN–0334. Madison, WI: U.S. Department of Agriculture, Forest Service, Forest Products Laboratory. 5 p. <https://doi.org/10.2737/FPL-RN-0334>
- Ross, R.J.; Wang, X. 2005. Quincy mine blacksmith shop—condition assessment of timbers. *Structure*. September 2005: 32–34.
- Ross, R.J.; Soltis, L.A.; Otton, P. 1998. Assessing wood members in the USS Constitution using nondestructive evaluation methods. *APT Bulletin*. 29(2): 21–25. <https://doi.org/10.2307/1504514>
- Ross, R.J.; Volny, N.; Pellerin, R.F.; Salsig, W.W.; Falk, R.H. 1999. Inspection of timber bridges with stress wave nondestructive evaluation tools—a guide for use and interpretation. General Technical Report FPL–GTR–114. Madison, WI: U.S. Department of Agriculture, Forest Service, Forest Products Laboratory.
- Ross, R.J.; Brashaw, B.K.; Wang, X. 2006. Structural condition assessment of in-service wood. *Forest Products Journal*. 56(6): 4–8.
- Ross, R.J.; Wang, X.; Senalik, C.A.; Allison, R.B.; Zhou, L. 2017. Nondestructive assessment of wood members from a historic viewing tower. Research Note FPL–RN–0349. Madison, WI: U.S. Department of Agriculture, Forest Service, Forest Products Laboratory. 8 p. <https://doi.org/10.2737/FPL-RN-349>
- Ross, R.J.; Senalik, C.A.; Wang, X. 2018. Nondestructive assessment of wood members in a viewing tower in Potawatomi State Park, Door County, Wisconsin, USA. Research Note. FPL–RN–0366. Madison, WI: U.S. Department of Agriculture, Forest Service, Forest Products Laboratory. 12 p. <https://doi.org/10.2737/FPL-RN-366>
- Wang X.; Wacker, J.P.; Ross, R.J.; Brashaw, B.K. 2008. Condition assessment of the main structural members of historic steam schooner Wapama. Research Paper FPL–RP–649. Madison, WI: U.S. Department of Agriculture, Forest Service, Forest Products Laboratory. <https://doi.org/10.2737/FPL-RP-649>
- Wilcox, W.W. 1978 Review of literature on the effects of early stages of decay on wood strength. *Wood and Fiber Science*. 9(4): 252–257.